


**Appendix A**

**Photographs Pertinent to TRA-63**





G1127-05




G1127-03

Figure A-1. A puddle of approximately 3 gal of radioactively contaminated water formed as soil was removed from the area around the 4-in. warm waste pipe.

30-in. warm  
waste pipeline

4-in. warm  
waste pipeline  
(WDC-605)

South →




G1127-01

30-in. warm  
waste pipeline

4-in. warm  
waste pipeline  
(WDC-605)

South →



G1127-02

Figure A-2. Photographs showing the 4-in. pipeline tie-in to the 30-in. pipeline during excavation for the 30-in. Warm Waste Pipeline Replacement Project.



G1127-06

Figure A-3. Approximate 1/2-in. shear in the 4-in. pipe.






Figure A-4. Photograph of 4-in. pipeline during 30-in. Warm Waste Pipeline Replacement Project.